

Date	October 28 th , 2020
Rev.	v121



To: All it may concern

NORTEK* CONTROL

This letter is to clarify a change made to Gefen's EXT-WHD-1080P-LR and EXT-WHD-1080-SR on both EU and US models.

The change was a minor change in the chipsets configuration only. The change was required to fix a configuration bug, that has no relation to the functionality of the chipset, or its performance. Firmware v121 was required to be implemented due to this chipset change noting that it will not be compatible with older hardware versions.

Specifically, there was no change in RF & Baseband schematics, and there is no need for repeating certification.

The change is identified with the following ECO codes label on the products:

EXT-WHD-1080P-SRR: 2260-225121U2605 EXT-WHD-1080P-SRR-EU: 2260-225121E2612 EXT-WHD-1080P-SRS: 2265-065121U2605 EXT-WHD-1080P-SRS-EU: 2265-065121E2612 EXT-WHD-1080P-LRS: 2270-045121U2605 EXT-WHD-1080P-LRS-EU: 2270-045121E2612 EXT-WHD-1080P-LRR: 2260-225121U2605 EXT-WHD-1080P-LRR-EU: 2260-225121E2612

In case of any future amendments to this product, a notice will be promptly distributed with explanation of the affected changes.

The products herein have been validated by Gef en. GEFEN abrand fullyowned by Nortek Control, a subsidary of Melrose Industries PLC.

Sincerely,

Nortek Control

Mike Payawal

Quality Assurance Engineer Manager